

**BUILDING SAFETY CERTIFICATE**

File No. 59


Date: 18/3/25

Certified that the existing building of **ADONI PUBLIC SCHOOL** at **Daspur Golamunda, District Kalahandi, Odisha**, is having block(s)/Floor(s) as per details below


Details of block in school	Block (1)	0
No. of Floor(s) in the Block	3	0

The building is owned/occupied by **ADONI PUBLIC SCHOOL** (name of the Institution) have complied with the building safety requirements in accordance with **National Building Code Rules**, and verified by the officers concerned of **Work Department, Dharamgarh (R&B) Sub Division** (Name of Department/ Govt.) on **18<sup>th</sup> March 2025** (date of inspection) in the presence of **Mr. Eramiyas Vaz C (Dean) ADONI PUBLIC SCHOOL at Daspur Golamunda, District Kalahandi, Odisha.** (Name and addresses of the Dean) and that the building /premises is fit for occupancy for running with effect from **18.03.2025** for a period of **01 Year (One)** in accordance with rule and subject to compliance

Issued on:

  
Signature with Seal  
Executive Engineer  
Dharamgarh (R&B) Sub Dvn

Designation: Executive Engineer Dharamgarh (R&amp;B) Sub Division

AttestedAttested

A.S-14-

Manager  
Adoni Public School  
Daspur, Kalahandi

PRINCIPAL  
Adoni Public School  
Daspur, Kalahandi