


PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

Letter No. 495

Date: 09/06/2025

It is certified that an inspection team headed by **Er. Biketa Majhi**, Executive Engineer from RWS&S, Sub-Division, Dharamgarh, District: Kalahandi, Odisha - 766015 inspected the **ADONI PUBLIC SCHOOL** at **Daspur, Golamunda, District: Kalahandi, Odisha - 766029** on Dt. 03.06.2025 and on the basis of Water Test Report bearing no. **SDWTLD-TR-06/2025-26** dated 04.06.2025 of Sub-Divisional Water Testing Laboratory, RWS&S, Sub-Division, Dharamgarh certified that **ADONI PUBLIC SCHOOL** (Name of school) has safe drinking water facilities for the students and members of staff of the institution. The school also maintains the hygienic sanitation conditions in the school building and the campus as per norms.

The above is valid for a period of 01 Years.


Signature with Seal:

Executive Engineer
RWS&S Sub-Division,
Dharamgarh

Name: **Er. Biketa Majhi**

Designation: Executive Engineer,

RWS&S, Sub-Division, Dharamgarh, Kalahandi, Odisha-766015


To,

ADONI PUBLIC SCHOOL

Daspur, Golamunda, District: Kalahandi, Odisha-766029


Manager
Adoni Public School
Daspur, Kalahandi

Attested


PRINCIPAL
Adoni Public School
Daspur, Kalahandi